

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5546</i>		LOCATION <i>1100 - 1/2 Street</i>			
DATE <i>11/18/37</i>		PURPOSE <i>Gen. Repairing to Ball Field.</i>			
ZONE		OWNER <i>Cardinal Field.</i>			
		ARCH'T.			
		CON'T'R. <i>G. H. Grippentrou</i>			
VAL. <i>1000⁰⁰</i>	STORIES	ROOMS	APTS. <i>2</i>	SIZE	
LIGHT SHAFTS			ELEVATOR SHAFTS		
VENT SHAFTS			BOILER ROOMS		
OWNER'S INSPECTOR			SPRINKLER SYSTEM		
LATH			GAS VENTS		
FIRE ESCAPES			CHIMNEYS		
STAND PIPES			SKYLIGHTS		

DATE

CONDITION OF WORK—REMARKS

1/25/37

2ND HSP. Frame for replaced sections
of Roof of Grand Stand blown off
by storm. All new timbers used and
additional braces, bolts and straps put
at ends and ends of adjoining trusses
O. K. H. Campbell

COMPLETE
AND O. K.

INSPECTOR