

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5639</i>	LOCATION <i>1022-3rd Street</i>				
DATE <i>2/9/37</i>	PURPOSE <i>Build new porch rear dwg.</i>				
ZONE	OWNER <i>Geo. S. Wheeler</i>				
	ARCH'T. <i>J. H. H.</i>				
	CON'T.R. <i>Owner</i>				
VAL. <i>300.00</i>	STORIES	ROOMS	APTS.	LOSS	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
2/8/37	2 ND HSP. Partial Frame Suck for Repair to new joints damaged by fire O.K.
2/15/37	2 ND HSP. Plat. of Frame ^{by} R. W. Campbell 4 TH HSP. Repairs Complete O.K.
2/24/37	COMPLETE AND O. K. <i>Alfred H. Campbell</i> INSPECTOR