

7134 4566-568

## BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$16.00

## TYPE BUILDINGS

|               |         |                                      |                 |             |  |
|---------------|---------|--------------------------------------|-----------------|-------------|--|
| PERMIT NO.    |         |                                      |                 |             |  |
| E-4316        |         | LOCATION 540 - San Antonio Way A-1   |                 |             |  |
| DATE          |         | PURPOSE Const. 4 room addn. to dwlg. |                 |             |  |
| Jul 3-63      |         | OWNER Eugene C. Ritenour Same        |                 |             |  |
| ZONE          |         | ARCH'T                               |                 |             |  |
|               |         | CONT'R Owner                         |                 | Same        |  |
| VAL. \$3,000. |         | STORIES                              |                 | APTS.       |  |
|               |         |                                      |                 | ROOMS       |  |
|               |         |                                      |                 | GL 2-0135   |  |
|               |         |                                      |                 | SIZE        |  |
|               |         |                                      |                 | 360 sq. ft. |  |
| INSP.         | DATE    | BLDG. TYPE                           | OCCUPANCY GROUP |             |  |
| FORM          | 7-18-63 | Calloway                             |                 |             |  |
| JOIST         | 7-25-63 | Roofs                                |                 |             |  |
| FRAME         | 7-20-63 | Roofs                                |                 |             |  |
| SHEET ROCK    | 8-7-64  | Roofs                                |                 |             |  |
| FINAL         | 2-4-65  | J. Bucate                            |                 |             |  |

| DATE    | SPECIAL CONDITIONS OF WORK — REMARKS                           |
|---------|--|
| 7-16-63 | P.T. 2x6 floor joint on west side must be<br>doubled up. Photo |
| 7-13-63 | Block in 2x8 ceiling joint <sup>Comp</sup>                     |
|         |  |
|         |  |
|         |  |
|         |  |
|         |  |
|         | COMPLETE<br>AND OK   |
|         | INSPECTOR  |