

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|------------------------------|--------------------------------------------------|
| PERMIT No. A-2390 | LOCATION 1624 - 14th Street |
| DATE 12/27/34 | PURPOSE Repairs to rear porch |
| ZONE Mult. Fam | OWNER (Shuler (Lessee)) |
| ARCH'T | CONT'R Hansen & Dutter |
| VAL. 200⁰⁰ | STORIES |
| | ROOMS |
| | APTS. |
| | SIZE |

| | |
|-------------------|------------------|
| Light Shafts | Elevator Shafts |
| Vent Shafts | Boiler Rooms |
| Owner's Inspector | Sprinkler System |
| Lath | Gas Vents |
| Fire Escapes | Chimneys |
| Stand Pipes | Skylights |

| DATE | CONDITION OF WORK—REMARKS |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1/7/35 | <p>Made final inspection of repairs to rear of 2-Story Bldg recently damaged by fire. All burned woodwork replaced with new materials. O.K. A. J. Campbell</p> |
| 1/7/35 | <p>COMPLETE AND O.K. <i>A. J. Campbell</i> INSPECTOR</p> |