5670 Fraklin BLVD 4-S

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
9-28-79	E. 125.00	G-9921 20.00 H 3808	Repair Damaged Elect. Pacific Tele. Poles	Pacific Telephone 3100 Power Inn Rd.	Arden Elect. P.O.Box 41097	Whitman	10-3-79
1-22-80	Elec $100.00	H-349 $20.00 H4080	Repl meter socket on SMUD & P.T.pole. 110 volt for P.T. cabel	Pacific Telephone	Arden Electric	Hubsmay	2/4/80

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
G-9921	R593F317				
G9921	R598F484 final				
H-349	R610F451				
H-349	final				