

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-7754</i>	LOCATION <i>1100 - 4th St.</i>			
DATE <i>1/26/38</i>	PURPOSE <i>Repairs to Bill Packer grandstand.</i>			
ZONE <i>Gen Com.</i>	OWNER <i>Cardinals.</i>			
	ARCH'T.			
	CONTR. <i>G. H. Grippenlog.</i>			
VAL. <i>1000⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
4/26/38	Made partial frame inspection of Repairs to Bleacher seats of Cardinal Baseball Stands.
	Installed 3x12" R.H. Continuous sill at foot of Stringers with 6"x8" Tie Timbers back to rear of seats and additional supports between
	M. Campbell
COMPLETE AND O. K.	INSPECTOR