

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <b>5350</b>	LOCATION <b>9<sup>th</sup> of Handerson Place, 5<sup>th</sup> St. San Diego</b>		
	PURPOSE <b>for 13<sup>th</sup> V Res Garage</b>	ROOMS <b>6</b>	APTS. <b>1</b>
DATE <b>10/14/24</b>	OWNER <b>G. B. Hendricks 2210 Center</b>		PHONE
ZONE	ARCH'T <b>Owner</b>		
	CONT'R <b>Owner</b>		
	VAL. <b>5000 -</b>	STORIES <b>1</b>	SIZE <b>34 x 47 - 20</b>

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
EX WALL	Joints						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
10/21/29	1 <sup>ST</sup> /HSP. <sup>Contractor changed brick plan opening to wood.</sup> Forms in place OK A.W. Campbell
11/2/29	2 <sup>ND</sup> /HSP. Frame " " A.W. Campbell
11/9/29	3 <sup>RD</sup> /HSP. INT. PART " " A.W. Campbell
12/5/29	4 <sup>TH</sup> /HSP. Work Completed O.K. A.W. Campbell
12/5/29	Note. Contractor installed outlet on 2 sides of garage on line side to conduct water on main side.
12/5/29	ISSUED CERTIFICATE OF OCCUPANCY
	<p style="text-align: center;">COMPLETED AND O.K.</p> <p style="text-align: right;">INSPECTOR</p>