

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-4859</i>	LOCATION <i>1025 - Front</i>					
DATE <i>9/19/36</i>	PURPOSE <i>Repairs to Brick Wall</i>					
ZONE <i>—</i>	OWNER <i>Joseph Crosby</i>					
	ARCH'T. <i>—</i>					
	CONTR. <i>Henry Redmond</i>					
VAL. <i>375⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE		
LIGHT SHAFTS				ELEVATOR SHAFTS		
VENT SHAFTS				BOILER ROOMS		
OWNER'S INSPECTOR				SPRINKLER SYSTEM		
LATH				GAS VENTS		
FIRE ESCAPES				CHIMNEYS		
STAND PIPES				SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
9/3/36	Notified Owners rear wall of Kelly was unsafe, and ready to fall. H. W. Campbell
9/19/36	Owner let Contract to West Contractors to take down and rebuild brick walls
10/15/36	Brick Walls rebuilt ^{OK}
10/15/36	<div style="display: flex; justify-content: space-between; align-items: center;"> <div data-bbox="299 819 431 857">COMPLETE AND O. K.</div> <div data-bbox="439 767 1019 895" style="font-family: cursive; font-size: 1.2em;"> Wallace W. Campbell </div> <div data-bbox="1159 837 1293 857">INSPECTOR</div> </div>