

R101 2604 - ind. file

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$269.50
 Ptn. of Lot 1 - See plot plan
 Florin Acres TYPE BUILDINGS *7154 7217-218 permitted plan*

PERMIT NO. **E-1528** LOCATION **6441 - Power Inn Road** *8102 71-11*
7119 7203 - 205 file A-4

DATE **Jun-11-62** PURPOSE **Const. grocery super market.**

OWNER **R. H. Hom 3700 - 2nd Avenue**

ZONE **M-2 IP** ARCH'T **Gordon Klippel 1623 - 10th St.**

CONTR **Winston Steel Works 4600-W. Cap. Ave.**

VAL \$150,000.	STORIES 1 & M.	ROOMS FR-16456	APTS.	SIZE 17,820 sq. ft.
-----------------------	---------------------------	-----------------------	-------	----------------------------

INSP.	DATE	BLDG. TYPE V-no hr.sp	OCCUPANCY GROUP F-2
-------	------	------------------------------	----------------------------

FORM *8-7-62* *Revised*

JOIST

FRAME *1-30-63* *Revised*

SHEET ROCK *2-11-63* *Barbato including W. side of 1st wall*

FINAL *2-18-63* *Barbato*

3-18-63 *Partial final Barbato* *Ent Com*

Barbato

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
10-9-62	OK reworking steel <i>Barbato</i>
10-11-62	OK reworking steel <i>had well</i> <i>Barbato</i>
11-26-62	Not ready for frame <i>Barbato</i>
1-4-63	no frame/girth <i>Barbato</i>
1-29-63	Checked girth <i>Barbato</i>
2-7-63	P4 Not ready <i>Combs</i>
2-14-63	Change of app does not comply. <i>Barbato</i>
3-28-63	Instructed survey on job about the 2 change of air per hour code <i>Barbato</i>
3-14-63	Exterior left on column, north side of bldg. <i>Barbato</i>
3-14-63	Pack up first door, incorrect, cannot be double acting. <i>Barbato</i>
3-14-63	Install first door, will put <i>Barbato</i>
	COMPLETE AND OK <i>Barbato</i>

COMPLETE
AND OK

Barbato