

R-99 FH62-H65

Lot 31 **BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD** \$46.00

Meadowview Gardens

TYPE BUILDINGS

| | | | | |
|----------------------|--|---------------|--------------------|----------------------|
| PERMIT NO. E-1213 | LOCATION 1981 - Quincy Avenue A-5 | | | |
| DATE May 1-62 | PURPOSE Const. dwelling & attached garage | | | |
| ZONE R-1 | OWNER Harry J. Buckman III 1700-S St. Apt.#5 | | | |
| | ARCH'T | | | |
| | CONTR Owner HI 7-6367 | | | |
| VAL. \$12,900. | STORIES 1 | ROOMS 6 | APTS. 525 gar. | SIZE 1313 sq. ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | |
| FORM | 5-15-62 | Filled | | |
| JOIST | 5-29-62 | Const | | |
| FRAME | 7-30-62 | Build | | |
| SHEET ROCK | 8-13-62 | Filled | | |
| FINAL | 4-17-63 | Geo. R. L. | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--|
| 7.30.62 | Pt Frame - All 2x6 Ceiling joists must be a 1x4 nailed on the top of each end. Two vents are required in a two car garage Gutter |
| 7.33.62 | Pt Frame - Firewall gar. Tight blocking Rools |
| 1.34.63 | Will call when ready for final Rools |
| 4.3.63 | Pt Locked Gutter |
| 4.10.63 | Pt Shows door in bath must be wcc glass SF 4-24.63 Rools |
| | COMPLETE AND OK INSPECTOR |