

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO.

4742

LOCATION

1747 Stockton

PURPOSE

Repair

PHONES

ISSUED
MAY 5 - 1929
SACRAMENTO
BUILDING DIVISION

Brown & Security

Walter B...

VAL. *257* STORIES ROOMS APTS. SIZE

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Hfd. Conc.		Floor Tests	
Fire Escapes			
Stand-pipes			

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="230 844 381 890">COMPLETED AND O. J.</p> <p data-bbox="967 875 1105 896">INSPECTOR</p>