

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>2311-A</b>	LOCATION <b>530 - Pico Way.</b>				
DATE <b>11/28/34</b>	PURPOSE <b>Const. 6 Rm. Frame Attached Det.</b>				
ZONE <b>2 - Fam</b>	OWNER <b>C. E. Ruby.</b>				
	ARCH'T <b>Owner</b>				
	CONT'R <b>C. E. Ruby.</b>				
VAL. <b>5000<sup>00</sup></b>	STORIES	ROOMS <b>6</b>	APTS.	See Plans.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
12/4/34	1 <sup>ST</sup> INSP. FORMS IN PLACE <i>OK</i> <i>AW Campbell</i>
12/18/34	2 <sup>ND</sup> INSP. PARTIAL FRAME. Only wanted to know if wall separating garage from rest of house is plastered with metal L & P. on both sides - There is metal L & P. required on W + C of garage. Correct <i>AW Campbell</i>
12/27/34	2 <sup>ND</sup> INSP. BAL. OF FRAME <i>OK</i> <i>AW Campbell</i>
12/31/34	3 <sup>RD</sup> INSP. EXT LATE IN PLACE <i>OK</i> <i>AW Campbell</i>
1/3/35	3 <sup>RD</sup> INSP. INT. LATE INC. WALL BKT. DWLG & GARAGE ATTACHED <i>OK</i> <i>AW Campbell</i>
2/19/35	4 <sup>TH</sup> INSP. DWLG & GARAGE ATTACHED TO DWLG <i>Completed</i> <i>AW Campbell</i>
2/19/35	Issued Final Insp & Cert. of Occ'y. <i>AW Campbell</i> Street cleaned up <i>OK</i>
2/19/35	COMPLETE AND O.K. <i>Allen H Campbell</i> INSPECTOR