

Sacramento Fire Department - Incident Report

Incident No : 000037508 Call# : 83307 Date: 08/23/00 Time: 10:41
Address : 1500 JANRICK AV
Type : BUILDING FIRE
Action Taken: VENTILATION, EXTINGUISH, SALVAGE, OVERHAUL
Property : 1-2 FAMILY RESIDENTIAL: TWO FAMILY
UBC : DWELLINGS AND LODGING HOUSES

Weather : 88 Degrees / Clear
Resources : 1 Engine, 2 Trucks
 : 1 Other Apparatus
 : 3 Fire Rescue Units
Fire Casualties : 1 CIV Injured

Fire Damage : Confined to structure of origin
Smoke Damage : Confined to structure of origin
Property Loss : \$20,000 Contents Loss :
Property Value : \$50,000 Contents Value:
Area of Origin : Personal service area
Caused by : No equipment involved
Form of Heat : Insufficient information
Ignition Factor : Insufficient information
Type of Material : Insufficient information
Form of Material : Insufficient information
Type of Material : Insufficient information
Form of Material : Insufficient information
Smoke Travel : Doorway, passageway
Other Factors : Acts or Omissions Insufficient information
Extinguished by : Water from hydrant, draft, standpipe
Structure Type : Building with one specific property use
Structure Status : In use
 : Occupied
Construction Type : Type V Wood Frame
Fuel Type : Composition
Number of Stories : 1

Level: A01

Detector Type : No detector
Extinguishing Sys: No extinguishing system
Report Author : F723