

|   |           |                                 |                 |       |  |                             |  |      |            |
|---|-----------|---------------------------------|-----------------|-------|--|-----------------------------|--|------|------------|
| 28, 29, 30 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD |           |                                 |                 |       |  | \$67.00                     |  |      |            |
| 21, 32, et al   |           |                                 |                 |       |  |                             |  |      |            |
| Cutter Industrial center  |           |                                 |                 |       |  |                             |  |      |            |
| TYPE BUILDINGS R-94<br>FH 31-444                                |           |                                 |                 |       |  |                             |  |      |            |
| PERMIT NO.  |           | E-461                           |                 |       |  |                             |  |      |            |
| LOCATION  |           | 1717 Stockton Blvd.             |                 |       |  | A-1                         |  |      |            |
| DATE  |           | Jan. 23, 62                     |                 |       |  |                             |  |      |            |
| PURPOSE   |           | Repair fire damage to warehouse |                 |       |  | F-2                         |  |      |            |
| OWNER   |           | John Pearl                      |                 |       |  | 1701 Stockton Blvd.         |  |      |            |
| ZONE  |           | C-4                             |                 |       |  |                             |  |      |            |
| ARCH'T  |           | Wallace Alexander               |                 |       |  | 302 Mitau Bldg              |  |      |            |
| CONTR   |           | Davis Const.                    |                 |       |  | 1700 Glenrose Ave. N. Sacto |  |      |            |
| VAL.  | \$19,100. | STORIES                         | 1               | ROOMS |  | APTS.                       |  | SIZE | 14950 S.F. |
| INSP.   | DATE      | BLDG. TYPE                      | OCCUPANCY GROUP |       |  |                             |  |      |            |
| FORM  |           |                                 |                 |       |  |                             |  |      |            |
| JOIST   |           |                                 |                 |       |  |                             |  |      |            |
| FRAME   | 2.2.62    | Reits                           |                 |       |  |                             |  |      |            |
| SHEET ROCK  | 2.13.62   | Reits                           |                 |       |  |                             |  |      |            |
| FINAL   | 4-25-63   | B. Balato                       | ent comm        |       |  |                             |  |      |            |

| DATE               | SPECIAL CONDITIONS OF WORK — REMARKS  |
|--------------------|---|
| 1-24-62            | Ok wilds on plates top of Column Feet   |
| 1-26-62            | Glu-lam Fabrication Certificate Approved A. McZellipis  |
| 2-12-62            | P. K. Anne - No plans Feet  |
| 11-8-62            | Numerous violations in final exam. S. File 11-19-62<br>talked to Mr. Beach, work well   |
| 11-19-62           | take care of a row over allures<br>bolt missing a glue lam<br>connection. Plywood outside<br>in front of blade. <sup>partial</sup> plates |
|                    |   |
|                    |   |
| COMPLETE<br>AND OK | INSPECTOR   |