

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-440</i>	LOCATION <i>1079 + 1089 - Perkins Way</i>			
DATE <i>12/5/39</i>	PURPOSE <i>Eject new dividers for</i>			
ZONE <i>2-Fam</i>	OWNER <i>Belle Eastburn</i>			
	ARCH'T. <i>Hadley & Hadley</i>			
	CONTR. <i>Hadley & Hadley</i>			
VAL. <i>5500</i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS			BOILER ROOMS	<i>1500 sq'</i>
OWNER'S INSPECTOR			SPRINKLER SYSTEM	<i>@ 300</i>
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE.	CONDITION OF WORK—REMARKS
12/6/39	1 ST /N.S.P. Forms in place ^{OK} AW Campbell
12/26/39	2 ND /N.S.P. Frame ^{OK} AW Campbell
1/2/40	3 RD /N.S.P. INT + EXT. LATH ^{OK} AW Campbell
3/12/40	4 TH /N.S.P. DWG. + Garage Completed ^{OK} AW Campbell
3/12/40	<p>COMPLETE AND O. K. <i>AW Campbell</i></p> <p style="text-align: right;">INSPECTOR</p>