

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>2725</i>	LOCATION <i>2715 to 30 East Pl</i>
DATE <i>5/7/31</i>	PURPOSE <i>Repair</i>
ZONE	OWNER <i>W.K. Co for Pederson</i>
	ARCH'T
	CONTR. <i>A. Alderson</i>

VAL.	STORIES <i>2</i>	ROOMS	APTS.	SIZE
------	---------------------	-------	-------	------

Steel Tested by	Elevator Shafts
Cement Tested by	Boiler Rooms
Owner's Inspector Rfcd. Conc.	Sprinkler System
	Floor Tests
Fire Escapes	
Stand Pipes	

DATE

CONDITION OF WORK—REMARKS

5/8/30

Inspection made this day on Electric
logie on sidewalk 14'3" above walk and
secured to bldg with 2 through bolts and wires
guy wires to face and cross face walk to roof.
O.K. A.H. Campbell

COMPLETED
AND O.K.

A.H. Campbell

INSPECTOR

5/8/30