

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

|                           |                                       |
|---------------------------|---------------------------------------|
| PERMIT NO.<br><i>2725</i> | LOCATION<br><i>2715 to 30 East Pl</i> |
| DATE<br><i>5/7/31</i>     | PURPOSE<br><i>Repair</i>              |
| ZONE                      | OWNER<br><i>W.K. Co for Pederson</i>  |
|                           | ARCH'T                                |
|                           | CONTR.<br><i>A. Alderson</i>          |

|      |            |         |       |       |      |
|------|------------|---------|-------|-------|------|
| VAL. | <i>241</i> | STORIES | ROOMS | APTS. | SIZE |
|------|------------|---------|-------|-------|------|

|                               |  |                  |  |
|-------------------------------|--|------------------|--|
| Steel Tested by               |  | Elevator Shafts  |  |
| Cement Tested by              |  | Boiler Rooms     |  |
| Owner's Inspector Rfcd. Conc. |  | Sprinkler System |  |
|                               |  | Floor Tests      |  |
| Fire Escapes                  |  |                  |  |
| Stand Pipes                   |  |                  |  |

DATE

CONDITION OF WORK—REMARKS

5/8/30

Inspection made this day on Electric  
logie on sidewalk 14'3" above walk and  
secured to bldg with 2 through bolts and wire  
guy wires to face and over fire walk to roof.  
O.K. A.H. Campbell

5/8/30

COMPLETED  
AND O.K.

Allan H. Campbell

INSPECTOR