

**BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

<b>PERMIT No.</b> <i>A. 2483</i>	<b>LOCATION</b> <i>516 - P Street</i>		
<b>DATE</b> <i>2/6/35</i>	<b>PURPOSE</b> <i>Remodel dwell for lease</i>		
<b>ZONE</b> <i>General Commercial</i>	<b>OWNER</b> <i>J. J. Silva</i>		
	<b>ARCH'T</b> <i>Frank J. A. F. Terra</i>		
	<b>CONT'R</b> <i>Frank J. A. F. Terra</i>		
<b>VAL.</b> <i>1400<sup>00</sup></i>	<b>STORIES</b> <i>2</i>	<b>ROOMS</b>	<b>APTS.</b> <i>4</i>
			<b>SIZE</b>

<b>Light Shafts</b>		<b>Elevator Shafts</b>	
<b>Vent Shafts</b>		<b>Boiler Rooms</b>	
<b>Owner's Inspector</b>		<b>Sprinkler System</b>	
<b>Lath</b>		<b>Gas Vents</b>	
<b>Fire Escapes</b>		<b>Chimneys</b>	
<b>Stand Pipes</b>		<b>Skylights</b>	

DATE	CONDITION OF WORK—REMARKS
4/17/35	Made Preliminary Insp. of 2-Story Family Dwlg damaged by Fire - Roof burned off and 2 <sup>nd</sup> Story Ceiling. A.W. Campbell
2/25/35	2 <sup>nd</sup> flr/HSP. Frame. Joist above - All burned timbers replaced with new materials. properly braced and nailed O. K. A.W. Campbell
2/26/35	3 <sup>rd</sup> flr/HSP; INT. LATH. Ceilings & Patching A.W. Campbell
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="349 1036 527 1089">COMPLETE AND O. K.</span> <span data-bbox="1275 1060 1459 1085">INSPECTOR</span> </div>