## CITY OF SACRAMENTO

1231 I Street, Sacramento, CA 95814

9909068 Permit No:

Insp Area:

Site Address: 6330 NORTH POINT WY SAC

Parcel No:

030-0790-011

Sub-Type: RES Housing (Y/N): N

CONTRACTOR FRED B CURTIS "4"5 [4] HAV

SACRAMENTO CA 95820

**OWNER** O CONNOR JOHN D/MAUREE 6330 NORTH POINT WY SACRAMENTO CA 95831

**ARCHITECT** 

	NSTRUCTION LENDING AG		m under penalty of perj	ury that there is a cons	truction lending age	ncy for the performanc
1313	er's Name		Lender'sAd	dress		
<. n : 1	ENSED CONTRACTORS DE	ion 3 of the Business a	nd Professions Code and	d my license is in full f	orce and effect.	
<b>L</b> .an	ise Tass 39 License Number	159577 1	Date 9/7/99	Contractor Signatus	e all	2
ÖW torker aldy S or the total	NER-BUILDER DECLARATION on greason (Sec. 7031.5. Business a tructure, prior to its issuance, also reaction for Contractors License Law (Chapter profession and the basis for the all tylification for them five hundred dol	ON: I hereby affirm and Professions Code: a quires the applicant for 9 (commencing with leged exemption. Any	n under penalty of perjuny city or county which such permit to file a single Section 7000) of Divis	ury that I am exempt h requires a permit to gned statement that he tion 8 of the Business	from the contractor construct, alter, imp or she is licensed p and Professions Co	ors License Law for the rove, demolish, or repair ursuant to the provision ode) or that he or she is
there said	as a owner of the property, or my employees with wages as their sole compensation, will do the work, and the structure is not intended or offer sale. Sec 7.44. Business and Professional Code: The Contractors License Law does not apply to an owner of property who builds or improvement, and who does such work himself or herself or through his/her own employees, provided that such improvements are not intended or offered aic. If, however, the building or improvement is sold within one year of completion, the owner-builder will have the burden of proving that he/she of saild or improve for the purpose of sale.)					
	L as owner of the property, am e The Contractors License Law doe actor(s) beensed pursuant to the Con	s not apply to an owne	with licensed contractor of property who build	ors to construct the pr ls or improves thereon	oject (Sec. 7044, B , and who contracts	usiness and Profession for such projects with
	Lam exempt under Sec	B & PC for	this reason:			
Date		Owner Sign	ature			
al m arpu	SSUING THIS BUILDING PERM casurements and locations shown or wate agreement relating to permissibility to permissibility of the violation of any provenent or the violation or t	the application or accordence or prohibited location	ompanying drawings and instructions for such improvement	d that the improvemer nts. This building peri	it to be constructed.	does not violate any lav
relan	ify that I have read this application ng to building construction and herb	y authorize representati	ve(s) of this city to ente	er upon the abovement	oned property for in	rdinances and state law spection purposes.
Date	2,5/88	Applicant/A	agent Signature	Loto		
WO	RKER'S COMPENSATION D  I have and will maintain a certificate the work for which the permi	ECLARATION: 11 to self-in:	ereby affirm under pen	alty of perjury one of t	he following declara	itions: f the Labor Code, forth
wh	1 have and will maintain workers' in this permit is issued. My workers'	compensation insuranceompensation insurance	ce, as required by Sect e carrier and policy nun	ion 3700 of the Labor ober are:	Code, for the perfo	ormance of the work fo
	Corne: CONTINENTAL CAS	SUALTY	Policy Number A	VC19124606K	Exp Date	04/26/2000
shai Minic	(this section need not be complete not employ any person in any man cut the workers' compensation prov	ner so as to become su	ibject to the workers' co	ompensation laws of (	California and agree	that if I should become
				1//		

FRIMINAL PENALTIES AND CIVIL FINES UP TO ONE HUNDRED THOUSAND DOLLARS (\$100,000) IN ADDITION TO THE COST OF COMPENSATION, DAMAGES AS PROVIDED FOR IN SECTION 3706 OF THE LABOR CODE, INTEREST AND ATTORNEY'S FEE.

## **SCHOEN ENGINEERING**

9524 BEDINGTON WAY SACRAMENTO, CA 95827 (916) 369 6866 LIC.# C042913

August 17, 1999



Cathy Curtis Roofing 7475 14<sup>th</sup> Avenue Sacramento, CA 95820

SUBJECT:

Roof inspection at 6330 North Point Way, Sacramento, CA 95831

Dear Cathy:

On August 11<sup>th</sup> 1999 I inspected the roof structure of the residence at the above mentioned address. The roof was of standard construction with 2x6 Douglas fir No. 2 rafters @ 2' o.c. with a span of 12'-4" in the second story roof attic areas and 8' in the vaulted area of the master bedroom. The master bedroom had a full dimension 4x12 ridge beam spanning 15'-3". In the first story there were 2x6 rafters 2' o.c. spanning 12' in the dinning room vault area and 2x6 rafters @ 16" o.c. with a span of 14 in the living room vault area. There was a 6x16 second support beam in the garage that spanned 19'. The garage door header was a 4x14 spanning 16'-3".


the following modifications need to be made prior to reroofing:


- \* The rake overhangs at the gable ends of both the second story and first story roof have shown some sagging as they are too long for the 2x4 outriggers installed. It will be necessary to install new 4x4 outriggers. The new 4x4 outriggers should be placed with one at the low end of the gable, one at the high end of the gable and one in the middle third of each verge board. The new outriggers can be installed in the same locations as the existing 2x4 outriggers or they may be installed in new locations (see attached detail).
- \* The rafters in the vault areas of the living room and dinning room areas are over span. These should be reinforced for the new roof loads. This can be done by doubling up the existing rafters with 2x6 Douglas fir No. 2 running continuous from the plate to the ridge and attaching them to the existing rafters with 16d common nails @ 16" o.c. (see attached detail).
- \* The ridge of the vaulted area between the dinning room area and the living room is not adequately supported. To support the ridge it will be necessary to cut out the existing 2x6 ridge board and install a 1-3/4"x9-1/2" microlam in its place. The microlam should extend from over the gable end wall to two rafter spaces beyond the beginning of the wall between the living room and kitchen. Attach the Microlam to the rafters with Simpson A35 framing angles one on each side of the rafter.

I would like to thank you for allowing me tho provide my services in this matter. Please let me know if I may be of further assistance.


Mark S. Schoen P.I

MSS:mss s-enggg/curfool ool





RAKE OVERHALLA OUTRIGGER



MIGRALIA PLOSE BOARD

OF CALIFORN