

R-55

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD F 2 37-2H2

**TYPE BUILDINGS** \$18,50

PERMIT NO. D-1805	LOCATION 380 Sandburg Dr.
	PURPOSE Const. 2-rooms & bath to rear of dwlg.
DATE Apr. 29, 59	OWNER D. Irvin
ZONE R-1	ARCH'T
	CONT'R Owner GL 7-0007

VAL. \$5,500	STORIES	ROOMS	APTS.	623 Sq.ft. <sup>SIZE</sup>
--------------	---------	-------	-------	----------------------------

INSP.	DATE	INSPECTOR
FORM	7-30-59	<i>R. Irvin</i>
JOIST	10-2-59	<i>Fuller</i>
FRAME	3-8-60	<i>Shumway</i>
LATH	9-16-60	<i>Fuller</i>
FINAL	11-21-61	<i>Berry</i>

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
2-10-60	P.I. Bldg. not wrapped. 2x8 ceiling joists not blocked. Shumway.
12-5-60	Not finished - will call when finished. Bury
	<p data-bbox="344 850 471 899">COMPLETE AND OK</p> <p data-bbox="1171 874 1298 899">INSPECTOR</p>