

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-8017.</i>	LOCATION <i>917-10th St.</i>			
DATE <i>4/17/41</i>	PURPOSE <i>Hang elec. sign.</i>			
ZONE	OWNER <i>Prestier Paint Co.</i>			
	ARCH'T.			
	CONTR. <i>Geo. C. Foss</i>			
VAL. <i>100⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
4/17/21	Made inspection on South Side V-Side
	Collected beam found in pit above
	Side walk & more timber 3/4 mile
	from face of Comb. Seams at back
	to face of H. OR R. H. 1/2 mile
	<div data-bbox="320 878 448 919" data-label="Text"> <p>COMPLETE AND O. K.</p> </div> <div data-bbox="1167 899 1305 923" data-label="Text"> <p>INSPECTOR</p> </div>