

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

|                             |                                    |                      |                   |
|-----------------------------|------------------------------------|----------------------|-------------------|
| PERMIT NO.<br><b>2989</b>   | LOCATION<br><b>6401 Greeter 64</b> | <b>3024 San Jose</b> |                   |
| DATE                        | PURPOSE<br><b>RE-PAINT</b>         | ROOMS<br><b>6</b>    | APTS.<br><b>1</b> |
| OWNER<br><b>R E Connell</b> | PHONE                              |                      |                   |
| ARCHT.                      | OWNER<br><b>Joe Bluck</b>          |                      |                   |
| CONTR.                      | DIVISION                           |                      |                   |
| MENTO                       | STORIES<br><b>2</b>                | SIZE<br><b>2200</b>  |                   |

ICE  
ZONE  
JUL 1  
SACR  
BUILDING

| FOUNDATION | STORY                   | BSMT | 1 | 2 | 3 | ROOF |                  |               |
|------------|-------------------------|------|---|---|---|------|------------------|---------------|
| Ex Wall    | Joints                  |      |   |   |   |      | Chimneys         | Cement Tests  |
|            | Beams and Girders       |      |   |   |   |      | Fire Place       |               |
| Int Wall   | Studs and Columns       |      |   |   |   |      | Gas Water Heater |               |
|            | Bridging Fire Stops     |      |   |   |   |      | Heater Closet    |               |
| Piers      | Fire Escape Stand Pipes |      |   |   |   |      | Furnace          | Window Courts |
|            | Metal Lath              |      |   |   |   |      | Boiler Room      |               |
|            | Stairs                  |      |   |   |   |      | Elevator Shaft   |               |

DATE

CONDITION OF WORK—REMARKS

7/16/28

1<sup>st</sup>/HSP. FRAMES IN PLACE. O.K. R.W. Campbell

7/1/28

2<sup>nd</sup>/HSP. Frame in place O.K. R.W. Campbell

8/22/28

3<sup>rd</sup>/HSP. INT. LATH O.K. R.W. Campbell  
metal lath in boiler drumCOMPLETED  
AND O. K.

INSPECTOR