

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-4515</i>	LOCATION <i>1175 - Robertson Way</i>
DATE <i>7/1/36</i>	PURPOSE <i>Erect new double garage</i>
ZONE	OWNER <i>Harry B. De Haven</i>
	ARCH'T. <i>HARRY B. DEHAVEN, State Architect's Office</i>
	CONTR. <i>Frank Williams</i>

VAL. <i>5150⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>1470 P1</i>
LATH	GAS VENTS	<i>@ 3.50</i>
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
7/14/36	1 ST / H.S.P. Frames in place. ^{OK} A.W. Campbell
8/7/36	2 ND / H.S.P. Frame ^{OK} A.W. Campbell
8/13/36	3 RD / H.S.P. INT & EXT LATH ^{OK} A.W. Campbell
10/9/36	4 TH / H.S.P. Dwg & Detached Garage ^{Completed OK} A.W. Campbell
10/9/36	Issued Final Insp & Certificate of Occupancy Stack cleaned up ^{OK} A.W. Campbell
10/9/36	COMPLETE AND O. K. <i>Alden W Campbell</i> INSPECTOR