

| | | | | | |
|--------------|------------|--|--------------------------------------|---------------|---------------|
| Lot #326 | | BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD | | | \$31.00 |
| Southgate #2 | | TYPE BUILDINGS | | R80 F128-199 | R79-F.345-356 |
| PERMIT NO. | D-7840 | LOCATION | 7766 - Shrader Circle a-5 | | |
| DATE | Feb. 24-61 | PURPOSE | Const. dwelling & att. gar. Plan #71 | | |
| ZONE | R-1 | OWNER | Mountain House & gard. 3350-Jola Cir | | |
| | | ARCH'T | HI 7-3072 | | |
| | | CONT'R | Fred Johnsen 2215-Capitol Ave | | |
| VAL. | \$10,400. | STORIES | 1 | ROOMS | 5 |
| | | APTS. | | 457-gar. | SIZE |
| | | | | 1,080 sq. ft. | |
| INSP. | DATE | INSPECTOR | | | |
| FORM | 2-27-61 | Barbato | | | |
| JOIST | 3-3-61 | Barbato | | | |
| FRAME | 4-14-61 | Barbato | | | |
| LATH | | | | | |
| FINAL | 8-9-61 | Berry | | | |

| DATE | SPECIAL CONDITIONS OF WORK—REMARKS |
|--------------------|--|
| 4-13-66 | P.T. Center joint not replaced - no flashing Porch roof brace missing |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |

