

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | |
|-----------------------------------|---|--|------------------------------|
| PERMIT NO. <i>A-907</i> | LOCATION <i>2504 - V. Street</i> | | |
| DATE <i>9/5/33</i> | PURPOSE <i>1 - private garage</i> | | PHONES <i>none</i> |
| ZONE <i>Mult. fam</i> | OWNER <i>Mrs. Mable Green</i> | | |
| | ARCH'T <i>Owner</i> | | |
| | CONT-R <i>Owner</i> | | |

| | | | | |
|---------------------------|----------------|--------------|--------------|-------------|
| VAL. <i>100.00</i> | STORIES | ROOMS | APTS. | SIZE |
|---------------------------|----------------|--------------|--------------|-------------|

| | | | |
|--------------------------|--|-------------------------|--|
| Light Shafts | | Elevator Shafts | |
| Vent Shafts | | Boiler Rooms | |
| Owner's Inspector | | Sprinkler System | |
| Lath | | Gas Vents | |
| Fire Escapes | | Chimneys | |
| Stand Pipes | | Skylights | |

| DATE | CONDITION OF WORK—REMARKS |
|---------|--|
| 9/13/33 | <p>Made Inspect. 7 p.m. on 9/13/33. 2 pieces installed wall. Diver. Not good man on site. Walls must be metal lath and plaster including ceiling. Also additional studs placed on South & East walls and concrete on west platform ground. R. W. Campbell</p> |
| 9/15/33 | <p>2ND / NSP. Frame OK A. W. Campbell</p> |
| 9/15/33 | <p>3RD / NSP. / HIT. Metal Lath Walls & Ceiling OK A. W. Campbell</p> |
| | <p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p> |