

CITY OF SACRAMENTO

1231 I Street, Sacramento, CA 95814

Site Address: 3825 38TH ST SAC

Parcel No: 0200034001

Permit No: 9804759

Insp Area: 3

Sub-Type: RES

Housing (Y/N): N

CONTRACTOR

DOUBLE D BUILDERS INC
6217 32 ST
NORTH HIGHLANDS CA

95660

OWNER

ARRIBA FRED A/JUNE M
5095 SCARBOROUGH WY
SACRAMENTO CA

95823

ARCHITECT

Nature of Work: FIRE REPAIR(DUPLEX)

CONSTRUCTION LENDING AGENCY : I hereby affirm under penalty of perjury that there is a construction lending agency for the performance of the work for which this permit is issued (Sec. 3097, Civ. C).

Lender's Name _____


Lender's Address _____

LICENSED CONTRACTORS DECLARATION: I hereby affirm under penalty of perjury that I am licensed under provisions of Chapter 9 (commencing with section 7000) of Division 3 of the Business and Professions Code and my license is in full force and effect.

License Class B

License Number 524046

Date 6/2/98

Contractor Signature 

OWNER-BUILDER DECLARATION: I hereby affirm under penalty of perjury that I am exempt from the contractors License Law for the following reason (Sec. 7031.5, Business and Professions Code; any city or county which requires a permit to construct, alter, improve, demolish, or repair any structure, prior to its issuance, also requires the applicant for such permit to file a signed statement that he or she is licensed pursuant to the provisions of the Contractors License Law (Chapter 9 (commencing with Section 7000) of Division 3 of the Business and Professions Code) or that he or she is

Sacramento Fire Department - Incident Report

Incident No : 980021206 Call# : 98046031 Date: 05/25/98 Time: 13:24
Address : 3825 38TH ST
Type : 11 BUILDING FIRE
Action Taken: 13 EXTINGUISH,SALVAGE,OVERHAUL
Property : 1-2 FAMILY RESIDENTIAL: SINGLE FAMILY
UBC : DWELLINGS AND LODGING HOUSES

Weather : 70 Degrees / Clear
Resources : 2 Engines, 1 Truck
Fire Casualties : None

Fire Damage : Confined to part of room or area of origin
Smoke Damage : Confined to structure of origin
Property Loss : \$2,000 Contents Loss : \$1,000
Property Value : \$45,000 Contents Value: \$10,000
Area of Origin : Kitchen area
Caused by : Stove/grill/fixed stationary surface unit
Form of Heat : Heat/properly operating electrical equip
Ignition Factor : Falling asleep
Type of Material : Fat,grease(food)
Form of Material : Cooking materials
Type of Material : Fat,grease(food)
Form of Material : Cooking materials
Smoke Travel : Doorway,passageway
Other Factors : Drowsiness
Extinguished by : Water carried on first in unit
Structure Type : Building with one specific property use
Structure Status : In use
Occupied
Construction Type: Type V - Wood Frame
Roof Type : Composition
Number of Stories: 1

Level: A01

Detector Type : Smoke detector - ionization
Power : Battery
Performance : Detector not in space of origin - did not operate
Reason Failed : Failure of power supply

Extinguishing Sys: No extinguishing system

Report Author : F395