

CITY OF SACRAMENTO

Permit No: 9808130

1231 I Street, Sacramento, CA 95814

Insp Area: 1

Site Address: 1301 D ST SAC

Sub-Type: RES

Parcel No: 0020084011

Housing (Y/N): N

CONTRACTOR

BOUEY PEST CONTROL
3639 - 4TH AVE
SACRAMENTO, CA

95817

OWNER

AUBURN TRUST
5855 AUBURN BL
SACRAMENTO CA

95841

ARCHITECT

Nature of Work: PEST REPAIR

CONSTRUCTION LENDING AGENCY: I hereby affirm under penalty of perjury that there is a construction lending agency for the performance of the work for which this permit is issued (Sec. 3097, Civ. C).

Lender's Name

Lender's Address

LICENSED CONTRACTORS DECLARATION: I hereby affirm under penalty of perjury that I am licensed under provisions of Chapter 9 (commencing with section 7000) of Division 3 of the Business and Professions Code and my license is in full force and effect.

License Class B0013 License Number PR2375 Date 8/21/58 Contractor Signature [Signature]

OWNER-BUILDER DECLARATION: I hereby affirm under penalty of perjury that I am exempt from the contractors License Law for the following reason (Sec. 7031.5, Business and Professions Code; any city or county which requires a permit to construct, alter, improve, demolish, or repair any structure, prior to its issuance, also requires the applicant for such permit to file a signed statement that he or she is licensed pursuant to the provisions of the Contractors License Law (Chapter 9 (commencing with Section 7000) of Division 8 of the Business and Professions Code) or that he or she is exempt therefrom and the basis for the alleged exemption. Any violation of Section 7031.5 by any applicant for a permit subjects the applicant to a civil penalty of not more than five hundred dollars (\$500.00);

I, as a owner of the property, or my employees with wages as their sole compensation, will do the work, and the structure is not intended or offered for sale (Sec. 7044, Business and Professional Code: The Contractors License Law does not apply to an owner of property who builds or improves thereon, and who does such work himself or herself or through his/her own employees, provided that such improvements are not intended or offered for sale. If, however, the building or improvement is sold within one year of completion, the owner-builder will have the burden of proving that he/she did not build or improve for the purpose of sale.)

I, as owner of the property, am exclusively contracting with licensed contractors to construct the project (Sec. 7044, Business and Professions Code: The Contractors License Law does not apply to an owner of property who builds or improves thereon, and who contracts for such projects with a contractor(s) licensed pursuant to the Contractors License Law).

I am exempt under Sec. B & PC for this reason:

Date Owner Signature

IN ISSUING THIS BUILDING PERMIT, the applicant represents, and the city relies on the representation of the applicant, that the applicant verified all measurements and locations shown on the application or accompanying drawings and that the improvement to be constructed does not violate any law or private agreement relating to permissible or prohibited locations for such improvements. This building permit does not authorize any illegal location of any improvement or the violation of any private agreement relating to location of improvements.

I certify that I have read this application and state that all information is correct. I agree to comply with all city and county ordinances and state laws relating to building construction and hereby authorize representative(s) of this city to enter upon the abovementioned property for inspection purposes.

Date 8/21/58 Applicant/Agent Signature [Signature] TOB BOUEY BOUEY PEST

WORKER'S COMPENSATION DECLARATION: I hereby affirm under penalty of perjury one of the following declarations:

I have and will maintain a certificate of consent to self-insure for workers' compensation as provided for by Section 3700 of the Labor Code, for the performance of work for which the permit is issued.

[X] I have and will maintain workers' compensation insurance, as required by Section 3700 of the Labor Code, for the performance of the work for which this permit is issued. My workers' compensation insurance carrier and policy number are:

Carrier STATE FUND Policy Number 428 PAID 5 CITY OF SACRAMENTO 199

(This section need not be completed if the permit is for \$100 or less) I certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the workers' compensation laws of California and that the person shall not become subject to the workers' compensation provisions of Section 3700 of the Labor Code, I shall fully comply with those provisions.

Date 8/21/58 Applicant Signature [Signature] BOUEY PEST SERVICE

WARNING: FAILURE TO SECURE WORKER'S COMPENSATION COVERAGE IS UNLAWFUL AND SHALL SUBJECT AN EMPLOYER TO CRIMINAL PENALTIES AND CIVIL FINES UP TO ONE HUNDRED THOUSAND DOLLARS (\$100,000) IN ADDITION TO THE COST OF COMPENSATION, DAMAGES AS PROVIDED FOR IN SECTION 3706 OF THE LABOR CODE, INTEREST AND ATTORNEY'S FEE.

THIS PERMIT SHALL EXPIRE BY LIMITATION IF WORK IS NOT COMMENCED WITHIN 180 DAYS.



**TERMITE SERVICE**  
**(916) 733-0520**


**DATE:** 8-10-98

**PROPERTY ADDRESS:** 1301 - D - Street, Sacramento, CA 95814

**REPORT#:** 6708

SECTION 1 ITEM(S)#		
1A.....	\$	785.00
1B.....	\$	180.00
4A.....	\$	290.00
4B.....	\$	315.00
4C.....	\$	70.00
4D.....	\$	185.00
10A.....	\$	1585.00
11A.....	\$	90.00
11B.....	\$	130.00
11E.....	\$	125.00
11G.....	\$	30.00
<b>TOTAL....</b>	<b>\$</b>	<b>3785.00</b>

SECTION 2 ITEM(S)#		
1C.....	\$	85.00
4E.....	\$	50.00
11D.....	\$	10.00
11F.....	\$	30.00
<b>TOTAL....</b>	<b>\$</b>	<b>175.00</b>



**ISSUED**  
 AUG 25 1998  
 CITY OF SACRAMENTO  
 DEVELOPMENT SERVICES DIV

**MINIMUM JOB PRICE** .....\$ 145.00

This estimate is subject to review after 60 days.

**ITEM(S):**

**COST:**


**AUTHORIZED BY:**

**PHONE#:**

# WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

This is an inspection report only - not a Notice of Completion

**ADDRESS OF PROPERTY INSPECTED**

BUILDING NO. 1301	STREET D Street	CITY Sacramento	ZIP 95814	COUNTY CODE 34	DATE OF INSPECTION 8-10-98	NUMBER OF PAGES 5
BOUEY PEST CONTROL 3639 - 4th Avenue Sacramento, CA 95817 (916) 733-0520					STATE OF CALIFORNIA DEPARTMENT OF CONSUMER AFFAIRS <b>STRUCTURAL PEST CONTROL BOARD</b> REPORT OF INSPECTION	
REGISTRATION # PR2375		REPORT # 6708	STAMP # 1595844	ESCROW # 1595844 V		

ORDERED BY: Guido Pfirrmann  
132 Avila Road, San Mateo, CA 94402


REPORT SENT TO: \_\_\_\_\_

PROPERTY OWNER: Guido Pfirrmann  
Above

PARTY IN INTEREST: \_\_\_\_\_

ORIGINAL REPORT <input checked="" type="checkbox"/> LIMITED REPORT <input type="checkbox"/> SUPPLEMENTAL REPORT <input type="checkbox"/> REINSPECTION REPORT <input type="checkbox"/>	*Original Stamp # _____ Date _____																																														
GENERAL DESCRIPTION: <u>2 Story frame residence</u>																																															
INSPECTION TAG POSTED: <u>Subarea</u>																																															
OTHER INSPECTION TAGS: _____																																															
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 60%;">1. SUBSTRUCTURE AREA</td> <td style="width: 40%;">Dry, accessible, See #1</td> </tr> <tr> <td>2. STALL SHOWER</td> <td>None</td> </tr> <tr> <td>3. FOUNDATIONS</td> <td>Concrete above grade</td> </tr> <tr> <td>4. PORCHES - STEPS</td> <td>See #4</td> </tr> <tr> <td>5. VENTILATION</td> <td>Appears adequate</td> </tr> <tr> <td>6. ABUTMENTS</td> <td>Columns, See 1G</td> </tr> <tr> <td>7. ATTIC SPACES</td> <td>Inspected</td> </tr> <tr> <td>8. GARAGES</td> <td>None</td> </tr> <tr> <td>9. DECKS - PATIOS</td> <td>None</td> </tr> <tr> <td>10. OTHER - INTERIOR</td> <td>See #10</td> </tr> <tr> <td>11. OTHER - EXTERIOR</td> <td>See #11</td> </tr> </table>	1. SUBSTRUCTURE AREA	Dry, accessible, See #1	2. STALL SHOWER	None	3. FOUNDATIONS	Concrete above grade	4. PORCHES - STEPS	See #4	5. VENTILATION	Appears adequate	6. ABUTMENTS	Columns, See 1G	7. ATTIC SPACES	Inspected	8. GARAGES	None	9. DECKS - PATIOS	None	10. OTHER - INTERIOR	See #10	11. OTHER - EXTERIOR	See #11	<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">RIDGE JACKS</td> <td></td> </tr> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">EXPOSED JOIST</td> <td></td> </tr> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">CELLULOSE BATT</td> <td></td> </tr> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">FLOOR OVER LEVELS</td> <td></td> </tr> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">WALL &amp; JOIST CONTACTS</td> <td></td> </tr> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">OTHER WOOD CONTACTS</td> <td></td> </tr> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">FLOOR OR GY EOT</td> <td></td> </tr> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">DRY WOOD TREATMENT</td> <td></td> </tr> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">SUBSTRATE TREATMENT</td> <td></td> </tr> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">FURTHER TREATMENT</td> <td></td> </tr> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">NOT TREATED</td> <td></td> </tr> <tr> <td style="writing-mode: vertical-rl; transform: rotate(180deg);">UNCOVERED AREAS</td> <td></td> </tr> </table>	RIDGE JACKS		EXPOSED JOIST		CELLULOSE BATT		FLOOR OVER LEVELS		WALL & JOIST CONTACTS		OTHER WOOD CONTACTS		FLOOR OR GY EOT		DRY WOOD TREATMENT		SUBSTRATE TREATMENT		FURTHER TREATMENT		NOT TREATED		UNCOVERED AREAS	
1. SUBSTRUCTURE AREA	Dry, accessible, See #1																																														
2. STALL SHOWER	None																																														
3. FOUNDATIONS	Concrete above grade																																														
4. PORCHES - STEPS	See #4																																														
5. VENTILATION	Appears adequate																																														
6. ABUTMENTS	Columns, See 1G																																														
7. ATTIC SPACES	Inspected																																														
8. GARAGES	None																																														
9. DECKS - PATIOS	None																																														
10. OTHER - INTERIOR	See #10																																														
11. OTHER - EXTERIOR	See #11																																														
RIDGE JACKS																																															
EXPOSED JOIST																																															
CELLULOSE BATT																																															
FLOOR OVER LEVELS																																															
WALL & JOIST CONTACTS																																															
OTHER WOOD CONTACTS																																															
FLOOR OR GY EOT																																															
DRY WOOD TREATMENT																																															
SUBSTRATE TREATMENT																																															
FURTHER TREATMENT																																															
NOT TREATED																																															
UNCOVERED AREAS																																															

DIAGRAM AND EXPLANATION OF FINDINGS ( This report is limited to structure or structures shown on diagram)



Inspected by OWEN BOUEY License No. FR10798 Signature *Owen Bouey*

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (213) 897-7838, (415) 557-9114, or (916) 263-2533.

You are entitled to obtain copies of all reports and completion notices on this property filed with the Board during the preceding two years upon payment of a \$2.00 search fee to: Structural Pest Control Board, 1422 Howe Ave., Ste. 3, Sacramento, California 95825-3280

Items 1 through 11 relate to locations, accessibility, conditions, infestations, and infections noted at the time of this inspection. Although we make a visual inspection, there are areas which are inaccessible for inspection. These include areas to which there is no access without defacing or tearing out lumber, masonry, or finished work. We do not move furniture, appliances, or raised floor coverings, nor do we routinely inspect the following areas: behind or under appliances, beneath floor coverings, under concrete slabs, the interiors of the hollow walls, bay windows, porte cocheres, columns, or abutments. Unless there are specific areas noted in the body of this report, any further inspection other than set forth in this report would be impractical.

This inspection only pertains to the structure(s) indicated on the diagram below. This report is a statement of conditions at the time of this inspection only. BOUEY PEST CONTROL does not certify the water integrity of roofs.

Please read all of the information contained with this report. We recommend all items in our report be completed. If work is performed by others, we cannot be responsible to certify absence or presence of infestations or infections if this Company is not contacted to reinspect prior to closing any areas. BOUEY PEST CONTROL will not guarantee work performed by others.

This report is not to be used to satisfy escrow requirements unless our inspection fee is paid. See the attached Work Order for the cost of recommended items. An authorized signature is necessary before any work can be performed.

#### REINSPECTION

A Reinspection of the structure (call within four months of the Original Inspection) will be performed by BOUEY PEST CONTROL if required by the person who ordered the Original Inspection. The cost for the Reinspection will not exceed the cost of the Original Inspection.

#### GUARANTEES

BOUEY PEST CONTROL Operators are licensed and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Food and Agriculture and the United States Environmental Protection Agency. Registration is granted when the State finds that, based on the existing scientific evidence, there are no appreciable risks if proper use conditions are followed or that the risks are outweighed by the benefits. The degree of risk depends upon the degree of exposure, so exposure should be minimized.

If within twenty-four (24) hours following application you experience symptoms similar to common seasonal illness comparable flu, contact your physician or Poison Control Center (listed below) and your pest control operator immediately. For further information, contact any of the following: your local office of BOUEY PEST CONTROL; for health questions, your County Health Department (listed below); for application information, your County Agricultural Commissioner (listed below); and for regulatory information, the Structural Pest Control Board at (916) 263-2540, 1422 Howe Avenue, Sacramento, CA 95825.

#### POISON CONTROL CENTER

Sacramento -1-800-876-4766

#### California County Agricultural Commissioners

Sacramento - (916) 875-6603

El Dorado - (530) 626-0308

Placer - (530) 889-7372

Yolo - (530) 666-8645

#### PESTICIDES THAT MAY BE USED ON YOUR PROPERTY DURING THE COURSE OF OUR WORK -

The names of materials actually used during each visit will be on the Completion Notice or the Invoice/Service slip. Active ingredients will be shown below in bold type:

PT 270 (Chlorphyros), **TIM-BOR** (Disodium Octaborate Tetrahydrate), **PREMISE 75** (Imidacloprid)

FUMIGANTS: Chloropicrin\*\*, Methyl Bromide\*\*\*, Vikane (Sulfuryl Flouride)\*\*\*.

\* - Effects of overexposure to this material can include nasal and respiratory irritation, dizziness, headache, and fatigue.

\*\* - Effects of overexposure to this material will cause teary eyes.

\*\*\* - Effects of overexposure to this material can include poor coordination, slurring words, and confusion.

**SECOND PAGE OF STANDARD REPORT OF THE PROPERTY LOCATED AT:**

Address of Property Inspected	1301	D Street	Sacramento
	Bldg. No.	Street	City
	1595844	8-10-98	6708
	Stamp No.	Date of Inspection	Co. Report (if any)

**\*NOTICE\*** The Structural Pest Control Board encourages competitive business practices among registered companies. Reports on this structure prepared by various registered companies should list the same findings, (i.e. - termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. Therefore, you have a right, and may wish, to seek a second opinion from another company since there may be alternative methods of correcting the findings on this report that may be less costly.

Under the California Mechanics Lien Law, any Structural Pest Control Operator who contracts to do work for any contractor, subcontractor, laborer, supplier, or other person who helps to improve your property but has not been paid for his work or supplies, has a right to enforce a claim against your property. This means that after a hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the debt. This can happen even if you paid your contractor in full if the subcontractor, laborers, or suppliers remain unpaid. We reserve the right to file a claim or lien against your property. Certain claimants, such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice". General contractors and laborers for wages do not provide this notice. A "Preliminary Notice" is not a lien against the property. Its' purpose is to notify you of persons who may have a right to file a lien against your property for debts that are not paid.

**BOUEY PEST CONTROL** cannot certify the roof nor do we offer any opinion as to its' quality.

The exterior surface of the roof will not be inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

Most exposed areas repaired will be painted or primed with one (1) coat of paint or primer. No guarantee is given on color match or quality of painting.

If damage extends into inaccessible areas, a Supplemental Inspection will be made and a Report issued outlining our findings, recommendations, and additional cost.

1 SUBSTRUCTURE

FINDING 1A: Fungus infection and damage noted in sill, ribbon, studs, sheathing, and rim joist extending up wall.

RECOMMENDATION 1A: Remove siding as needed. Remove and replace sill, ribbon, studs, sheathing, and joist.

SECTION 1.

FINDING 1B: Fungus infection and damage noted in framing.

RECOMMENDATION 1B: Remove and replace framing.

SECTION 1.

FINDING 1C: Cellulose debris noted in the subarea.

RECOMMENDATION 1C: Remove cellulose debris.

SECTION 2.

4 PORCHES

FINDING 4A: Fungus infection and damage noted in girder, siding, and stud at front porch.

RECOMMENDATION 4A: Remove and replace girder, siding, and stud.

SECTION 1.

FINDING 4B: Earth-wood contact and fungus infection at siding base at front porch.

RECOMMENDATION 4B: Remove and replace siding.

SECTION 1.

SECOND PAGE OF STANDARD REPORT OF THE PROPERTY LOCATED AT:

Address of Property Inspected	1301	D Street	Sacramento
	Bldg. No.	Street	City
	1595844	8-10-98	6708
	Stamp No.	Date of Inspection	Co. Report (if any)

Continued.....

FINDING 4C: Fungus infection noted in front stairs.

RECOMMENDATION 4C: Remove surface fungus and treat area with the registered fungicide, Timbor (Sodium Borate).

SECTION 1.

FINDING 4D: Earth-wood contact and fungus infection noted at stair base and post bases.

RECOMMENDATION 4D: Cut off base and install masonry footing.

SECTION 1.

FINDING 4E: Front stairs are damaged at base.

RECOMMENDATION 4E: Repair stairs as needed.

SECTION 2.

10 INTERIOR

FINDING 10A: Damaged underlayment noted in both bathrooms.

RECOMMENDATION 10A: Remove toilet and damaged underlayment. Install underlayment as necessary and new vinyl floor covering. Install new seal and reset the toilet.

If damage extends into the subfloor, walls, or beyond the finished floor, or if plumbing requiring repair is disclosed, a Supplemental Inspection will be made and Report issued outlining our findings, recommendations, and additional cost.

SECTION 1.

11 EXTERIOR

FINDING 11A: Fungus infection and damage noted in rear porch cover.

RECOMMENDATION 11A: Remove rear porch cover, cut posts at rail top, and install caps.

SECTION 1.

FINDING 11B: Fungus infection noted in soffits.

RECOMMENDATION 11B: Repair soffits. Remove surface fungus and treat area with the registered fungicide, Timbor (Sodium Borate).

SECTION 1.

FINDING 11C: Fungus infection and damage noted in windows.

RECOMMENDATION 11C: Owner to consult a licensed window contractor for further inspection and recommendation for repair.

SECTION 1.

FINDING 11D: Earth-wood contact noted.

RECOMMENDATION 11D: Lower soil.

SECTION 2.

SECOND PAGE OF STANDARD REPORT OF THE PROPERTY LOCATED AT:

Address of Property Inspected	1301	D Street	Sacramento
	Bldg. No.	Street	City
	1595844	8-10-98	6708
	Stamp No.	Date of Inspection	Co. Report (if any)

Continued.....'

FINDING 11E: Fungus infection and damage noted in siding.  
RECOMMENDATION 11E: Remove and replace siding and cut siding base.  
SECTION 1.

FINDING 11F: Leak at tub drain.  
RECOMMENDATION 11F: Repair leak.  
SECTION 2.

FINDING 11G: Fungus infection noted in column and column trim.  
RECOMMENDATION 11G: Remove fungus. Remove surface fungus and treat area with  
the registered fungicide, Timbor (Sodium Borate).  
SECTION 1.