

R-71

Lt. 105-106 BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD F-432-452

Lemon Hill Tct. ^{C-39} TYPE BUILDINGS \$66.50 R71 F520
R71 E777
R-73 A-4 485

| | |
|----------------------|--|
| PERMIT NO. D-6035 | LOCATION 6039 Stockton Blvd. |
| DATE Jun. 20, 60 | PURPOSE Const automotive shop E-4 |
| ZONE C-2 | OWNER Cal- Gas Equipment |
| | ARCH'T |
| | CONT'R Erickson Const 977 Arden WA 2-6721 |

| | | | | |
|----------------|--------------|------------|-------|---------------------|
| VAL. \$32,000. | STORIES 1 | ROOMS 2 | APTS. | SIZE 7050 Sq.ft. |
|----------------|--------------|------------|-------|---------------------|

| INSP. | DATE | INSPECTOR |
|-------|-----------------------------|--|
| FORM | 6-21-60 6-22-60 | Florr slab - Fuller Fuller |
| JOIST | 7-1-60 8-2-60 | Set up steel - 3 panels OK Fuller Berry |
| FRAME | 8-2-60 | Berry |
| LATH | 8-9-60 | Barlato |
| FINAL | 2-7-61 | Berry |

| DATE | SPECIAL CONDITIONS OF WORK—REMARKS |
|----------|---|
| 6-23-60 | Tilt-up OK Fuller |
| 6-28-60 | Tilt-up 3 Panels OK Fuller |
| 6-29-60 | Tilt-up OK Fuller |
| 6-30-60 | Tilt-up panels - 2 - OK Fuller |
| 7-20-60 | Columns OK. Shumway |
| 7-28-60 | Roof Diaphragm - Shumway |
| 8-3-60 | Form OK. Berry |
| 9-19-60 | Inspection and on job. |
| 9-22-60 | Work on install wire glass & metal frame windows, also fix window on fire wall, "Firefall between garage and office - insulate |
| 11-17-60 | No final as yet - Bantals |
| | |
| | <p data-bbox="283 859 414 906">COMPLETE AND OK</p> <p data-bbox="1084 880 1215 906">INSPECTOR</p> |