

R-309 F-9738 g

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$12.00

TYPE BUILDINGS

| | | | | | |
|----------------------|---------|---|-----------------|-------|---------------|
| PERMIT NO. H-2796 | | LOCATION 1338 - Teneighth Way A-2 (24) | | | |
| DATE Aug. 12-71 | | PURPOSE Install partitions on 2nd story dwlg. | | | |
| ZONE R-1 | | OWNER Dr. Spensley Same | | | |
| | | ARCH'T | | | |
| | | CONTR A-1 Constr. 5608 - Rickey Drive | | | |
| VAL. \$800. | | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | | PHONE (O) (C) |
| FORM | | | | | 421 2237 |
| JOIST | | | | | |
| FRAME | 9-13-71 | <i>[Signature]</i> | | | |
| SHEET HOOK | 9-16-71 | <i>[Signature]</i> | | | |
| FINAL | 11-8-71 | <i>[Signature]</i> | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|---|
| 9-15-71 | <i>P. Abs. no one home, unable to make</i> |
| 11-4-71 | <i>at home - not home inspection gullies</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | <div style="display: flex; justify-content: space-between;"> COMPLETE AND OK INSPECTOR </div> |