

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>5436</i>	LOCATION <i>367 Homeland</i>	<i>1616 Y St.</i>
	PURPOSE <i>Brk into 1 by 2 stories</i>	PHONES
DATE <i>10/25/29</i>	OWNER <i>Edw. J. Butler</i>	<i>2159 - 2nd</i>
ZONE	ARCH'T <i>Edw. J. Butler</i>	
	CONT'R <i>Edw. J. Butler</i>	

VAL. <i>1600</i>	STORIES <i>1</i>	ROOMS <i>1</i>	APTS.	SIZE <i>2 1/2 x 10 1/2 = 25</i>
---------------------	---------------------	-------------------	-------	------------------------------------

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand-pipes			

DATE	CONDITION OF WORK—REMARKS
10/25/29	1 <sup>st</sup> Insp Forms in place & OK P.H. Rutter
11/13/29	2 Insp Forms " " 4 P.H. Rutter
11/19/29	3 Insp Int & Ext Ltr OK P.H. Rutter
12/10/29	4 Insp Final OK P.H. Rutter
	Street cleaned up.
COMPLETED AND O. K.	P.H. Rutter Inspector