### CITY OF SACRAMENTO 1231 I Street, Sacramento, CA 95814

Permit No: 0108896

Insp Area:

Site Address: 700 SOTANO DR SAC

262-0290-029

Sub-Type:

RES Housing (Y/N): N

Parcel No: **CONTRACTOR** 

<u>OWNER</u>

**ARCHITECT** 

GUTIERREZ BASILIO & MARIA ARCELIA 700 SOTANO DR

SACRAMENTO CA 95833

Nature of Work: REROOF T/O REPAIR DAMAGED TRUSSES INSTALL 6SQ LIGHTWEIGHT

TILE	
CONSTRUCTION LENDING A of the work for which this permit is issued.	<b>GENCY</b> : I hereby affirm under penalty of perjury that there is a construction lending agency for the performance used (Sec. 3097, Civ. C)
Lender's Name	l ender's Address
	<b>DECLARATION:</b> I hereby affirm under penalty of perjury that I am licensed under provisions of Chapter System 3 of the Business and Professions Code and my license is in full force and effect.
incense Class reense Numb	per Date Contractor Signature
following reason (Sec. 7031 5, Busines any structure, prior to its issuance, also of the Contractors License Law (Chapter)	TION: I hereby affirm under penalty of perjury that I am exempt from the contractors License Law for the sa and Professions Code, any city or county which requires a permit to construct, alter, improve, demolish, or repair requires the applicant for such permit to file a signed statement that he or she is licensed pursuant to the provisions or 9 (commencing with Section 7000) of Division 8 of the Business and Professions Code) or that he or she is exempted exemption. Any violation of Section 7031.5 by any applicant for a permit subjects the applicant to a civil penalty of 0000.
for sale (Sec. 7044, Business and Profe and who does such work himself or he	my employees with wages as their sole compensation, will do the work, and the structure is not intended or offered ssional Code: The Contractors License Law does not apply to an owner of property who builds or improves thereonerself or through his/her own employees, provided that such improvements are not intended or offered for sale. If, is sold within one year of completion, the owner-builder will have the burden of proving that he/she did not build or
The Contractors License Law does recontractor(s) licensed pursuant to the Contractor	exclusively contracting with licensed contractors to construct the project (Sec. 7044, Business and Professions Code: of apply to an owner of property who builds or improves thereon, and who contracts for such projects with a ontractors License Law).
I am exempt under Sec	B & PC for this reason
Date 7-6-0	XOwner Signature 12001110 Autorial
IN ISSUING THIS BUILDING PER measurements and locations shown on private agreement relating to permissib	MIT, the applicant represents, and the city relies on the representation of the applicant, that the applicant verified all the application or accompanying drawings and that the improvement to be constructed does not violate any law or le or prohibited locations for such improvements. This building permit does not authorize any illegal location of any vate agreement relating to location of improvements.
relating to building construction and her	on and state that all information is correct. I agree to comply with all city and county ordinances and state laws rby authorize representative(s) of this city to enter upon the abovementioned property for inspection purposes.
Pate /- / 2 6 /	Applicant/Agent Signature LOTCE She trearly
WORKER'S COMPENSATION	<b>DECLARATION:</b> I hereby affirm under penalty of perjury one of the following declarations: icate of consent to self-insure for workers' compensation as provided for by Section 3700 of the Labor Code, for the
I have and will maintain workers this permit is issued. My workers' com-	compensation insurance, as required by Section 3700 of the Labor Code, for the performance of the work for which pensation insurance carrier and policy mander are: 2
Carrier	*MCHBURHU() DS, PLANNING Exp Date
shall not employ any person in any ma	eted if the permit is for \$100 or less). I certify that in the permits of the work for which this permit is issued, I inner so as to become subject to the workers' compensation laws of California and agree that if I should become ovisions of Section 3700 of the Labor Code, I shall forthwith comply with those provisions.
Date /-/ (	CApplicant Signature & TORTHE & HITCHAY
WARNING. FAILURE TO SECURE CRIMINAL PENALTIES AND CIVIL	WORKER'S COMPENSATION COVERAGE IS UNLAWFUL AND SHALL SUBJECT AN EMPLOYER TO FINES UP TO ONE HUNDRED THOUSAND DOLLARS (\$100,000) IN ADDITION TO THE COST OF

COMPENSATION. DAMAGES AS PROVIDED FOR IN SECTION 3706 OF THE LABOR CODE, INTEREST AND ATTORNEY'S FEE.

#### **OWNER-BUILDER VERIFICATION**

## ATTENTION PROPERTY OWNERS

An owner-builder building permit has been applied for in your name and bearing your signature.

Please complete and return this information in the envelope provided at your earliest opportunity to avoid unnecessary delay in processing and issuing your building permit. No building permit will be issued until this verification is received.

1. I personally plan to provide the major labor and materials for construction of the pro- Improvement (yes) or no)						
2.		have/have not)signed an application fo building permit for the proposed work.				
	I have contracted with the following person (firm) to provide the proposed construction:					
	Name		_Address			
	City	Telephone				
	Contractors Lic	ense No.				
4.	I plan to provide portions of the work, but I have hired the following person to coordinate, Supervise, and provide the major work.					
	NameAddress					
	CityTelephone					
	Contractors Lice	ense No				
5.	I will provide some of the work but I have contracted (hired) the following to provide the Work indicated:					
	Name	Address	Phone	Type of work		
<del></del>						
Si	gned Povili	- Dwherren				
	b Address 70		DP-			
D۵	ermit No.	088910				

# **Pacific Consulting Engineers**

July 9, 2001 JUL 1 2 2001

Sacramento Building Division

Mr. & Mrs. Gutierrez

700 Sotano Dr.

Sacramento, CA 95833

Sacramento, CA 95833

Sacramento, CA 95833

RE: Re-roof at your residence on 700 Sotano Dr., Sacramento, CA 95833 This inspection and letter is our Job # 01-874.

Per your request, on July 9, 2001, I performed a visual inspection of existing roof framing at the aforementioned residence. The purpose was to determine if the existing roof framing is acceptable to support a light weight tile instead of the existing wood shake. The existing roof framing consisted of Pre-manufactured trusses spaced at 24" c.c.. The trusses were constructed of 2x4 df framing members.

The residence is a 2 story structure with 4 bedrooms upstairs and the typical living areas (kitchen, dining, living, family room) plus one bedroom/den and a garage at the lower story. Attachment #1 shows a sketch of the roof plan with approximate dimensions.

Based on the inspection, please be advised that it is structurally acceptable to remove the existing wood shake roofing material that weighs approximately 3 psf and replace it with a light weight Tile (6.0 psf or less – 600# per square) on the aforementioned residence. The new material is approximately 3.0 psf heavier and will not adversely affect the existing roof structure.

During the inspection it was noted that the bottom chord of the exposed trusses over the garage had been damaged and reinforced. Two of the trusses had cracks and separation, in the mid point of the bottom chord, at the point were the web members met the bottom chord. One of the trusses had a crack in the bottom chord where it tied to the top chord over the right wall of the garage.

Attachment #1 (sketch of the roof plan) shows the location of the damaged trusses. Attachment #2 shows the repair details. Attachment #3 has the calculations regarding the truss repair details.

Please note the following regarding the truss repair details ....

Make truss repairs after removing existing wood shakes and prior to placing new roof covering.

- Detail 1:
- Place wood glue (such as Elmers Wood Glue) on the full mating surface of the existing truss and new bottom chord brace.
- 2) Pre-drill lead holes for all #10 wood screws, to prevent splitting of the lumber, with 1/8" dia drill bit.
- 3) Coat screws with liquid soap prior to installing.


Gutierrez Page 2 July 9, 2001

<u>Detail 2:</u>
1) Place wood glue (such as Elmers Wood Glue) on full mating surface of the exiting truss and new plywood gusset.

Plywood gusset is to be a minimum of 48" wide and is to be made from 3/4" (21/32" min) APA Rated plywood. Oriented with the face grain parallel to the bottom chord. Place as close as possible to the end of the truss (at least to inside face of wall), and is to be sized to match the depth of the truss (within ½") at all points.

Thus, it is my professional opinion that providing the aforementioned repairs are made, the removal of the existing wood shake and the placement of the light weight tile will not have an adverse affect on the structural integrity of the existing structure.


If you have any questions or need further clarification on these matters please feel free to contact me at (916) 564-6028.




Jeffrey E. Hofmann, P.E.

GUTTEREZ- REPOSE 7/9/01 JEH 01-874 NOTE: SEE ATTACHMENT 2 FOR GARAGE TRUSS REPAIR, DETAILS, 50 SHEETS 100 SHEETS 200 SHEETS GAL Repair Beoken Bottom CHOND @ exposed trusses over gar wl Detail () 22 REPAIR END OF TRUSS @ BROKEN BOTTOM CHORO W/DETAIL(2) 201 221 ROOF PLAN GUTIERREZ RESID 700 SOTANO SACRAMENTO, CA PACIFIC CONSULTING ENGINEERS 2150 BELL AVE., SUITE 145 SACRAMENTO, CA 95838

3/5





# **Pacific Consulting Engineers**

2150 Bell Ave., Suite 145 ● Sacramento, CA 95838 ● (916) 564-6028 ● Fax: (916) 564-6029

September 10, 2001

Mr. & Mrs. Gutierrez 700 Sotano Dr. Sacramento, CA 95833



RE: Re-inspection of Roof Repairs at your residence on 700 Sotano Dr., Sacramento, CA 95833. This inspection and letter is our Job # 01-874.

As requested, on August 31, 2001, I inspected the repairs to the existing roof framing over the garage, that were recommended in my original report. The purpose was to determine if the repairs were made per my original report.

Please be advised that the repairs made to the trusses either met or exceeded the recommendations in my original report. The plywood gussets were placed on the correct truss.

If you have any questions or need further clarification on these matters please feel free to contact me at (916) 564-6028.

Sincerela

Jeffrey E. Hofmann, P.E.