

WARD 2

AREA
3-S
JOB
ADDRESS

5610 Freeport Blvd.

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
4-9-81	E \$500.00	I-984 \$20.00	Sewer Disconnect/Comm	Burger King Corp. 1333 Lawrence Exp Santa Clara, Ca.	0 & S Const. 5330 Primrose Dr. 229	<i>James H. [unclear]</i>	
4-30-81	E \$50.	I-1497 \$Gratuis	Install Elec. Sign Cir	Burger King 5610 Freeport Blvd.	Sacto. Signs 2745 Grosby Way	<i>William [unclear]</i>	5/27/81
4-30-81	Sign \$3500.	S-10136 \$105.	Install Sign	Burger King 5610 Freeport Blvd.	Sacto. Signs 2745 Grosby Way	<i>William [unclear]</i>	4/10/81
4-30-81	Sign \$4620.	S-10137 \$122.	Install Sign	Burger King 5610 Freeport Blvd.	Sacto. Signs 2745 Grosby Way	<i>William [unclear]</i>	4/10/81
4-30-81	Sign \$699.	S-10138 \$30.	Install Sign	Burger King 5610 Freeport Blvd.	Sacto. Signs 2745 Grosby Way	<i>William [unclear]</i>	4/10/81
4-30-81	Sign \$660.	S-10139 \$30.	Install Sign	Burger King 5610 Freeport Blvd.	Sacto. Signs 2745 Grosby Way	<i>William [unclear]</i>	4/10/81
4-30-81	Sign \$480.	S-10140 \$20.	Install Sign	Burger King 5610 Freeport Blvd.	Sacto. Signs 2745 Grosby Way	<i>William [unclear]</i>	4/10/81
4-30-81	Sign \$320.	S-10141 \$20.	Install Sign	Burger King 5610 Freeport Blvd.	Sacto. Signs 2745 Grosby Way	<i>William [unclear]</i>	4/10/81
4-30-81	Sign \$320.	S-10142 \$20.	Install Sign	Burger King 5610 Freeport Blvd.	Sacto. Signs 2745 Grosby Way	<i>William [unclear]</i>	4/10/81
5-21-81	BP \$6000.	I-1986 \$131.	Install overhead & underground piping.	Burger King Corp. 5610 Freeport Blvd.	American Auto. Fire 7683 Cook Ave. C.H.	<i>James H. [unclear]</i>	5/28/81
							CALLED BY PERMITTEE NO FINAL INSPECTION

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
I-984		I-1986		I-1497	R71 9841
S-10142	R07 IF 246 - 253	S-10140	R07 IF 246 - 253	S-10147	R71 9841
S-10140	R07 IF 246 - 253	S-10139	R07 IF 246 - 253	S-10137	R71 9841
S-10138	R07 IF 246 - 253	S-10137	R07 IF 246 - 253	S-10136	R71 9841
S-10136	R07 IF 246 - 253	S-10135	R07 IF 246 - 253	S-10134	R71 9841
I-1497	R07 IF 246 - 253	S-10133	R07 IF 246 - 253	S-10132	R71 9841
S-10142	R07 IF 246 - 253	S-10141	R07 IF 246 - 253	S-10140	R71 9841
S-10140	R07 IF 246 - 253	S-10139	R07 IF 246 - 253	S-10137	R71 9841
S-10138	R07 IF 246 - 253	S-10137	R07 IF 246 - 253	S-10136	R71 9841
S-10136	R07 IF 246 - 253	S-10135	R07 IF 246 - 253	S-10134	R71 9841
I-1497	R07 IF 246 - 253	S-10133	R07 IF 246 - 253	S-10132	R71 9841

Handwritten notes on the right side of the table, including "R71 9841" and other markings.

Handwritten notes at the bottom left of the table, including "10651291" and "000001".