

R-257 F410-415

Lot #114		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$52.00
Southgate Park #2		TYPE BUILDINGS			
PERMIT NO.	G-3000				
DATE	APR-4-69	LOCATION	5520 - Tangerine Avenue A-5 (49)		
ZONE	R-1	PURPOSE	Const. dwelling & attached garage		
		OWNER	Ray Winnegar 5908 - Stanley Avenue		
		ARCH'T	482-1120		
		CONTR	Owner	Same	
VAL.	\$14,900.	STORIES	1	ROOMS	
				APTS.	441-gar. SIZE
					1,548 sq. ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP		PHONE (O) (C)
FORM	4-9-69	Bole			
JOIST					
FRAME	4-30-69	Bole			
SHEET ROCK	5-5-69	Bole			
FINAL	6-23-69	Bole			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
4-8-69	Pt mudcells not laid out
	11 round promoters of ^{dist} submission
4-10-69	Pt old cement
4-25-69	7 K salts missing on mudcells
	Inj well must be treated. K salts
4-29-69	Pt from not ready
4-28-69	Pt unable to check dust work See case
6-20-69	Pt not ready
	<p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p>