

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

Card 2

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA 6-S		FINAL INSPECTIONS	
		2001 Point West Way							BUILDING BY	
LEGAL DESCRIPTION		OCCUP. GR.		CONST TYPE		VAR. NO.		FIRE ZONE		
		B-2		III-1HR				3		
TITLE AND NAME			ADDRESS		ZIP	CITY LIC. NO.		TEL. NO.		
ELECTRICAL BY									DATE	
GEN. CONTR.									DATE	
ELEC. CONTR.									DATE	
PLBG. CONTR.									DATE	
MECH. CONTR.									DATE	
ARCH. ENGR.									DATE	
OWNER									DATE	
CONST. LOAN LENDER									DATE	
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
								CENSUS TRCT. NO.		
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT		HOW USED	

NATURE OF WORK:-

PERMIT NO. S.P. -		MICROFILM RECORD			
ISSUED BY					
ISSUANCE DATE		PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO
VALUATION \$		INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$		JOB FILE	REEL NO.	FRAME NO:-	TO
S.M.I. FEE \$					
PLAN CK. FEE \$					
SEWER INCL. FEE \$					
PERMIT FEE \$		REMARKS AND/OR VARIANCES			
\$					
\$					
TOTAL FEES \$					

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
11/1/77	B. \$ 1250.00	E-8773 \$ 40.00	Planter retaining wall at restaurant bldg	Red Lion Motor Inn	M. Daniels Const	Thompson	5-17-78
4/5/78	P. \$ 3500.00	F-2675 \$ 78.00	Installation of addition	Red Lion Motor Inn	ABC Plumbing	Still	5-17-78
8/31/78	E. \$ 200.00	G-8312 \$ 20.00	Install power pole	Red Lion	Thundersbird Elec	Syllaasen	9/5/78
1/19/79	E. \$ 50.00	G-597 \$ gratis	Install circuits for office-comm	Red Lion Motor Inn	Owners		
1/18/79	Sign \$ 500.00	S-9419 \$ 20.00	Sign-comm	Red Lion Motor Inn	Owner	Treurn	5-7-80
1/18/79	Sign \$ 500.00	S-9420 \$ 20.00	Sign-comm	Red Lion Motor Inn	Owner	Treurn	5-7-80
7/31/79	P. \$6700	G7346 \$140	Irrigation for guested Lion wing Comm	same	owner	DeGruin	9-13-79
9/29/80	B \$3,000	H-7262 \$80.00	Repair of fire damage	Thunderbird/Red Lion	Owner		
1-12-82	BME \$450000	I 10111 \$1432	Int. Renovation	Red Lion Motor Inn	Same	Head	3-8-83

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
E-8773	R525R220	G7346	R584 F030-31	E-8773	R525R220	G7346	R584 F030-31
F-2675	R519R250			F-2675	R519R250		
E-8773	R525R220	G7346	R699F62	E-8773	R525R220	G7346	R699F62
F-2675	R525R220	S941		F-2675	R525R220	S941	
F-8312	R536 R516	H-7262	R641R419	F-8312	R536 R516	H-7262	R641R419
G-597	R525R296	F 10111C	R 704 F 347-356	G-597	R525R296	F 10111C	R 704 F 347-356
S-9419	R525R296			S-9419	R525R296		
S-9420	R525R296			S-9420	R525R296		