

(2) 176-4408-409 2

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$31.00

TYPE BUILDINGS

PERMIT NO. F-1637	LOCATION 5070 - Teichert Avenue		A-1
DATE Aug 31-65	PURPOSE Const. 2-story addn. & cov. patio to dw.	OWNER Robert Sterling same	
ZONE R-1	ARCH'T	CONTR <i>17</i> Kelly McClure 1012-Morse Avenue IV3-4	
VAL. \$7,600.	STORIES	ROOMS	APTS. 77-patio 721 sq. ft. SIZE 2
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP PHONE (O) (C)
FORM	9-7-65	<i>Chapin</i>	
JOIST			
FRAME	10-28-65	<i>Chapin</i>	
SHEET ROCK	11-3-65	<i>Chapin</i>	
FINAL	9-6-66	<i>C. Hammond</i>	

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
10-1-65	(1) Frame - (1) 1st. story must have solid sheathing on exterior walls. (2) Question approval on metal brace (3) Racking around shower below. (4) Racking for stairs + carpet under stairs. (5) Min. head clearance 6'6" at 2nd landing (case not equal) (6) Frame around fireplace chimney R. Larsen
10-31-65	Pt. Home - 4th floor on job <i>Chapin</i>
11-11-65	Pt. Home - Decked <i>Rosen</i>
6-24-66	Pt. Not Home. Left note to call <i>Chapin</i>
7-5-66	Pt. First - pack a water - handrail <i>Rosen</i>
8-20-66	Pt. First - 1/2" long size pack a water wire <i>Rosen</i>
	COMPLETE AND OK INSPECTOR