

CARD # 3

15

JOB ADDRESS

8801 Folsom Blvd.

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
✓ 10-9-81	BME \$6700. Suite #105	I-5306 \$140.	✓ Int. remodel office.	The Cook Co. 2020 Hurley #405	Owner 2020 Hurley #405	Williams 11/2/81 Hammer 11/19/81 Reynolds 11/2/81	
✓ 10-9-81	BME \$12700.	I-5305 \$194.	Const. corridor in wing C.	The Cook Co. 2020 Hurley	Owner 2020 Hurley	Ross 2/11/82 Hammer 2/16/82 Lacey 2/16/82	
10-16-81	BMPE \$7020 Ste 130	I-5440 \$149.	Complete office interior ste 130	The Cook Co 2020 Hurley Way	Owner	Williams 11/2/81 Reynolds 11/3/81 Hammer 11/3/81	
✓ 10-16-81	BME \$17,450 Ste 175	I-5441 \$239.	Complete office interior Ste 175	The Cook Co 2020 Hurley Way	Owner	Williams 11/2/81 Reynolds 11/3/81 Hammer 11/3/81	
✓ 10-16-81	BME \$7,020. Ste 130	I-5440 \$149.	Complete office interior ste 130	The Cook Co 2020 Hurley Way	Owner	Hammer 11/3/81 Reynolds 11/3/81 Williams 11/17/81	
✓ 11-20-81	BP \$450.	I-6182 \$20.	Instal Fire sprinkler outlets in lines at roof	The Cook Co. 2020 Hurley	American Auto. Fire 7683 Cook Ave. C.H.	Fuller 3/18/82 No Plans - Check Fuller 2/16/82	
N 11/2/81	BP \$2000.00	I-5746 \$101.25	Install sprinklers	Cook Co.	American Autom Fire	Fuller 3/18/82	

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
I-5306	R695F175-182	I-5306	R715F236		
I-5305	R695F175-182				
I-5746	R692 F109	I-5440	R715F237		
I-5441					
I-5440	R695F175-182	I-5441	R715F238		
I-6182	R696F370				
I-5305	R715F234				
I-6182	R715F235				

