

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|-----------------------|--|
| PERMIT NO. 235 | LOCATION 514 - 12 th St. |
| DATE 12/1/52 | PURPOSE Gen. Rep. in Bank |
| OWNER J.P. Kelly | PHONES |
| ZONE G.C. | ARCH'T |
| | CONT-R Owner |

VAL.

300

STORIES

ROOMS

APTS.

SIZE

| | | | |
|-------------------|--|------------------|--|
| Light Shafts | | Elevator Shafts | |
| Vent Shafts | | Boiler Rooms | |
| Owner's Inspector | | Sprinkler System | |
| Lath | | Gas Vents | |
| Fire Escapes | | Chimneys | |
| Stand Pipes | | Skylights | |

| DATE | CONDITION OF WORK-REMARKS |
|----------|---|
| 12/5/32 | 1 st Insp. PIERS FOR 3 Columns in New Center border O.K. <i>Mc Campbell</i> |
| 12/15/32 | 2 nd Insp. Made also inspection of Repairs and Reinforcing of Roof Trusses, also 3 Steel Columns with Corbels and bracing. 7"x14" Built up border. Additional Braces installed and all braces re- nailed and made safe. <i>Mc Campbell</i> |
| 12/15/32 | 3 rd Insp. Patching of plastering, where cornice fell off due to deflection of Trusses. <i>Mc Campbell</i> |
| | COMPLETE AND O. K. INSPECTOR |