

DATE	CONDITION OF WORK—REMARKS
6/13/27	1 ST /VSP. Contractor removed all Turned Timbers <i>FILE 2858</i>
6/23/27	2 ND /VSP. New Ceiling J. Rafters etc installed <i>All Campbell</i>
10/1/27	Place of timbers destroyed by fire
9/27/27	3 RD /VSP. LATH of interior frame & walls down & patches encasing. <i>All Campbell</i>
7/26/27	4 TH /VSP. Repairs to Dmly completed
7/26/27	COMPLETED AND O. K. <i>Alden H Campbell</i> Inspector