

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>No CHANGE</i>		LOCATION <i>3842 Stockton Blvd</i>			
DATE <i>June 14 1937</i>		PURPOSE <i>Extend Partition to Ceiling rear of</i>		PHONES <i>5016</i>	
ZONE <i>Remodel</i>		OWNER <i>M. N. DeBerry</i>			
VAL.		ARCH'T		CONT-R	
<i>75⁰⁰</i>		OWNER <i>OWNER</i>			
STORIES		ROOMS		APTS.	
SIZE					
Light Shafts		Elevator Shafts			
Vent Shafts		Boiler Rooms			
Owner's Inspector		Sprinkler System			
Lath		Gas Vents			
Fire Escapes		Chimneys			
Stand Pipes		Skylights			

DATE	CONDITION OF WORK--REMARKS
	<p data-bbox="297 847 445 893">COMPLETE AND O. K.</p> <p data-bbox="1039 872 1188 893">INSPECTOR</p>