

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. 534	LOCATION <i>San Francisco</i> 3277 Montgomery		
DATE	PURPOSE <i>Add 2nd Floor</i>	ROOMS	APTS.
	OWNER <i>Leo Banker</i>	PHONE	

SACRAMENTO BUILDING DIVISION JUN 3 - 1927	ARCH'T	
	CONT'R	<i>Quinn</i>
VAL.	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joints						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
8/ /27	1 ST /NSP. Forms. Notified Owner to widen footing for Block Fence Walls. H. D. Dwyer
9/15/27	2 ND /NSP. Frame for Rd. on Rear of K. H. W. Campbell
" " "	Owner digging Trench & widening footings K. H. W. Campbell
9/29/27	3 RD /NSP. INT. LATH O. K. N. W. Campbell

COMPLETED
AND O. K.

Inspector