

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-1057</i>	LOCATION <i>3908-20th Ave</i>			
DATE <i>10/13/33</i>	PURPOSE <i>Make alterations & repairs to dwell.</i>			
ZONE <i>2-Fam</i>	OWNER <i>H. E. Stewart</i>			
	ARCH'T <i>C. J. Hopkinson</i>			
	CONT-R			
VAL. <i>850⁰⁰</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK—REMARKS
10/17/33	1 st /N.S.P. Forms for Addition on each side of Ditch on rear. Also refers to old foundation. <i>OK</i> <i>W. Campbell</i>
10/20/33	2 nd /N.S.P. Forms for above. <i>OK</i> <i>W. Campbell</i>
10/30/33	3 rd /N.S.P. INT. LATH ^{new lathwork & patching} <i>OK</i> <i>W. Campbell</i>
11/29/33	4 th /N.S.P. Additions, Structures and Repairs to Ditch. Completed <i>OK</i> <i>W. Campbell</i>
11/22/33	COMPLETE AND O. K. <i>W. Campbell</i> INSPECTOR