

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-33725</i>	LOCATION <i>1938 - Stockton Blvd.</i>			
DATE <i>Oct 5-51</i>	PURPOSE <i>Remodel inter. bldg.</i>			
ZONE	OWNER <i>Dr. W. Kinkas</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>300</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	COMPLETE AND O. K.

INSPECTOR