

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-14975</i>	LOCATION <i>3335 - Stockton Blvd.</i>
DATE <i>1/14/46</i>	PURPOSE <i>Erect new Sew. station</i>
ZONE <i>-</i>	OWNER <i>Sidewater Assoc. Oil Co.</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>11996 00</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
1/21/26	15 th Insp Forms for New Service Station O.K. A.W. Campbell
	COMPLETE AND O. K. INSPECTOR