

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT No. <i>H-2617</i>	LOCATION <i>3235 - Johnson Blvd.</i>			
DATE <i>2/23/35</i>	PURPOSE <i>Erect Bill Board PHONES</i>			
OWNER <i>Mrs J. H. Forest</i>	ARCH'T <i>W. H. P. Co.</i>			
ZONE <i>1</i>	CONTR <i>W. H. P. Co.</i>			
VAL. <i>2500</i>	STORIES	ROOMS	APTS.	SIZE

Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

DATE	CONDITION OF WORK-REMARKS
2/25/35	Made deep of 1-Paul Poster Board erected 12ft back of property line properly braced in place
	O.K. - A.W. Campbell
2/25/35	COMPLETE AND O.K. <i>William H. Campbell</i> INSPECTOR