

② 210 7176-1777

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

DOUBLE FEE

PERMIT NO. F-6413	LOCATION 5700 - South Land Park Drive A-3	
DATE Feb 10-67	PURPOSE Repair damage at entrance of church	OWNER Parkside Church — same
ZONE R-1	ARCH'T	CONTR Owner same
VAL. \$300.	STORIES	ROOMS
		APTS.
		SIZE
INSP.	DATE	BLDG. TYPE V-1 shr.
FORM		OCCUPANCY GROUP B-2
JOIST		PHONE (O) (C)
FRAME	<p><i>Cancel because new permit # F-948 covers this permit. retained 1-26-68</i></p>	
SHEET		
ROCK		
FINAL		



DATE	SPECIAL CONDITIONS OF WORK — REMARKS
5-1-67	<p>           Cement was sampled - no imp. Eff.             down there (holes) are D.F. shot in concrete             &amp; extend up 1 1/2" Cracks are standing near             Eff. Division. Bellows does not extend down             in two doors. No eff. signs. Fish             in center of pipe - will bend noise             Chapin         </p>
COMPLETE AND OK	INSPECTOR

