

② 210 7176-1777

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

DOUBLE FEE

PERMIT NO. F-6413	LOCATION 5700 - South Land Park Drive A-3			
DATE Feb 10-67	PURPOSE Repair damage at entrance of church			
	OWNER Parkside Church — same			
ZONE R-1	ARCH'T OWNER CONTR Owner same			
VAL. \$300!	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE V-1 shr.	OCCUPANCY GROUP B-2	PHONE (O) (C)
FORM				
JOIST				
FRAME				
SHEET				
ROCK				
FINAL				

*Cancel because  
new permit # F-948  
covers this permit.  
retained  
1-26-68*



DATE	SPECIAL CONDITIONS OF WORK — REMARKS
5-1-67	<p>           Cement was sampled - no imp. Eff.             down there (holes) are D.F. shot in concrete             &amp; extend up 1 1/2" Cracks are standing near             Eff. Division. Bellows does not extend down             in two doors. No eff. signs. Fish             in center of pipe - will bend noise             Chapin         </p>
COMPLETE AND OK	INSPECTOR

