

R 320 F 217-219

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$78.00

Parcel 35

A.B. Davis Homestead Farms **TYPE BUILDINGS**

PERMIT NO. H-6841		LOCATION 6807 - San Joaquin Street A-4			
DATE May-8-72		PURPOSE Const. 2-story dwlg. & att. garage			
ZONE R-1		OWNER Frank A. Bruner 5441 - U St.			
ARCH'T		CONTR Owner Same 454 2815			
VAL. \$20,000.		STORIES 2	ROOMS	APTS.	449-gar. SIZE 1,313 sq. ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM					
JOIST					
FRAME	10-6-72	<i>Hank Korte</i>			
SHEET	10-24-72	<i>Hammans</i>			
ROCK					
FINAL	1-10-74	<i>J. Lewis</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
6-30-72	at Lake Fuller
8-28-72	Pt frame - not ready / - studs wire not OK ext. windows Fuller
9-28-72	1) no plans on job 2) floor joist not blocked Pt frame 3) studs not toe-tied 4) diaphragm incorrect 5) other items need correcting - Hammond
10-2-72	Pt frame not ready Hammond
1-11-73	Pt. framed - S/R incorrect Fuller
	COMPLETE AND OK INSPECTOR