

R240 E-5-17

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$164.00

TYPE BUILDINGS

R251 Full
E557

PERMIT NO. G-605	LOCATION 6010 - Stockton Blvd. A-4 (46.01)			
DATE June-11-68	PURPOSE Const. new addition to Pepper Mill restau-			
ZONE C-2	OWNER Larry Iniguez 6000-Stockton Blvd. /rant.			
	ARCH'T Lee McGlade 2011 - Arden Way			
	CONT'RM. J. Bambery Inc. 2223 - Dale Avenue			
VAL. \$63,000.	STORIES	ROOMS	APTS.	SIZE 3,196 sq. ft.
INSP.	DATE	BLDG. TYPE V No. Hr.	OCCUPANCY GROUP B-3	PHONE (O) (C) 925-3506
FORM	6-20-68	Calloway	7-11-68	OK slab - Chopin
JOIST				
FRAME	8-14-68	Full		
SHEET ROCK	9-4-68	Full		
FINAL	7-12-68	Dana Fuller		Cont.

DATE	SPECIAL CONDITIONS OF WORK — REMARKS	
7-9-68	Tilt-up OK - North wall - Reels	
7-15-68	OK Sakers cc. #3 + 4	Reels
7-16-68	OK #1-2 south wall	Reels
7-25-68	OK column steel, rear wall	Karpis
7-26-68	OK column steel Wash cc.	Reels
7-28-68	OK roof & wall steel	Reels
8-14-68	OK clear	Reels
8-22-68	OK Staircase, plans not on	Reels
8-28-68	Just work not on	Clear
8-28-68	OK frame, inspect pit area	Clear
8-30-68	OK St. not ready	Reels
9-3-68	Clearance, not correct	Reels
12-17-68	OK TRANS CONNECTIONS	Reels
12-19-68	COMPLETE if not ready	Reels
	COMPLETE AND OK	INSPECTOR