


| BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD | | | | | |
|--|--|---|--------|------|--|
| TYPE BUILDINGS | | | \$8.50 | | |
| PERMIT NO. G-42-56 | LOCATION 1480 Sutterville Road | | | | |
| DATE May 11/56 | PURPOSE Repairs to Existing Dwelling | | | | |
| ZONE | OWNER Robert W. Blair (2780 Land Park Drive) | | | | |
| | ARCH'T | | | | |
| | CONTR Owner | | | | |
| VAL. \$1500.00 | STORIES | ROOMS | APTS. | SIZE | |
| INSP. | DATE | INSPECTOR | | | |
| FORM | | | | | |
| JOIST | | | | | |
| FRAME | | | | | |
| LATH | | | | | |
| FINAL | 8/21/56 |  | | | |

| DATE | SPECIAL CONDITIONS OF WORK—REMARKS |
|--------------------|------------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |