

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. H-4023	LOCATION 1209 - Robertson Way			
DATE 3/14/36	PURPOSE Erect new building			
ZONE Two Fam.	OWNER Triangle Bldg. Inc.			
	ARCH'T. George W. ...			
	CONT'R. Triangle Bldg. Inc.			
VAL. 7,500 <sup>00</sup>	STORIES 2	ROOMS 7	FPTS. 7	SIZE Du Pless
LIGHT SHAFTS		ELEVATOR SHAFTS	Code @ 350	
VENT SHAFTS		BOILER ROOMS	1779 <sup>01</sup>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	\$6226 <sup>00</sup>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
3/17/36	1 <sup>ST</sup> / N.S.P. Frame in place <sup>OK</sup> M. W. Campbell
5/11/36	2 <sup>ND</sup> / N.S.P. Frame for Dry only <sup>OK</sup> M. W. Campbell
6/5/36	3 <sup>RD</sup> / N.S.P. EXT. PATH " " <sup>OK</sup> M. W. Campbell
11/8/36	3 <sup>RD</sup> / N.S.P. " " on Garage <sup>OK</sup> M. W. Campbell
11/10/36	3 <sup>RD</sup> / N.S.P. INT. WORK 2 <sup>ND</sup> STY <sup>OK</sup> M. W. Campbell
11/11/36	3 <sup>RD</sup> / N.S.P. " " 1 <sup>ST</sup> " <sup>OK</sup> M. W. Campbell
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="297 847 428 888">COMPLETE AND O. K.</span> <span data-bbox="1110 868 1239 888">INSPECTOR</span> </div>